



Picture 1 – Rowley Brothers Dairy, 45 John Rowley Rd., Milton, VT – 05/15/13
Woody vegetation growth on the bank of the main manure pit.



Picture 2 – Rowley Brothers Dairy, 45 John Rowley Rd., Milton, VT – 05/15/13
Location of drain inlet to the silage leachate collection system (covered in solids).



Picture 3 – Rowley Brothers Dairy, 45 John Rowley Rd., Milton, VT – 05/15/13
View from covered drain in picture #2 (looking southeast toward barns and main manure pit)



Picture 4 – Rowley Brothers Dairy, 45 John Rowley Rd., Milton, VT – 05/15/13
Displaced drain cover to silage leachate collection system (at the smaller silage bunker).



Picture 5 – Rowley Brothers Dairy, 45 John Rowley Rd., Milton, VT – 05/15/13
Temporarily uncovered silage pile at the heifer grazing and gathering farm.